



## Way Cover Preventative Maintenance

Way cover failure occurs most often due to a lack of simple preventive maintenance.

Here are 5 ways you can keep your machine running efficiently as well as save money on way cover repair and replacement:

1. If you have an extra hose, attach it and direct it to properly flush chips off of way covers. If not, spray down all way covers at least weekly.
2. Take an emery cloth and wipe down the way covers that have built up residue on them, so they are smooth and clean to keep chips from sticking. This keeps the way covers sliding freely.
3. Pull back the way covers and clean under them. Be sure to get in the corners where each slat slides.
4. Silicone all way covers to prevent coolant and chips from going underneath them.
5. Replace any wipers that are damaged as needed.